

PFE ORIGINAL



SDMS DocID 2189757



(b) (4)
[REDACTED]@tetrattech.c
om>

11/27/2007 02:05 PM

To: Mitch Cron/R3/USEPA/US@EPA
cc
bcc
Subject: FW: safety light

Mitch- see Phil's message below-

Andy

-----Original Message-----

From: Young, Phil
Sent: Tuesday, November 27, 2007 1:37 PM
To: (b) (4)
Subject: RE: safety light

I see no issues. For Survey Units 21 and 22, all of the results appear to be at or below background.

Phil

-----Original Message-----

From: Frebowitz, Andy
Sent: Tuesday, November 27, 2007 10:46 AM
To: Bailey, Lawson; Young, Phil
Subject: FW: safety light

See below- I attached Amy's spreadsheet- we're talking about survey units 21 and 22

Thanks

Andy

-----Original Message-----

From: Cron.Mitch@epamail.epa.gov [mailto:Cron.Mitch@epamail.epa.gov]
Sent: Monday, November 26, 2007 9:07 PM
To: Frebowitz, Andy
Subject: safety light

Andy: Can you have phil/lawson look at the soil scanning/stat. measurement data and perform a quick eval. of the adjacent residential properties. Any sign of an immediate threat to human health that requires action now? Let me know, thanks, Mitch

Mitch Cron
Remedial Project Manager
U.S. Environmental Protection Agency
Mail Code 3HS22
1650 Arch Street
Philadelphia, PA 19103-2029
(215) 814-3286
cron.mitch@epa.gov